

DGUV V3

Feuerwehr: ALTENSITTENBACH



Geschirrmobil / LAU-FA 265 / TÜV 02/24

Datum: 12.09.2023

Seite: _____

	Prüfling:	S-Art:	Sichtprüf.	R - PE		R - ISO		IEA		N. s. T.		IB EDV		Funktion:
				i.O.	Fehler	i.O.	Fehler	i.O.	Fehler	i.O.	Fehler	i.O.	Fehler	
1	KS5 25 400V/230V / Fi	I	✓	✓	≥ 0,5Ω	✓	≥ 1MΩ	✓	≤ 3,5mA	✓		✓	≤ 0,5mA	✓
2	Geschirrspüler	I	✓	✓	≥ 0,5Ω	✓	≥ 1MΩ	✓	≤ 3,5mA	✓		✓	≤ 0,5mA	✓
3	V.3m 400V	I	✓	✓	≥ 0,3Ω	✓	≥ 1MΩ	✓	≤ 3,5mA	✓		✓	≤ 0,5mA	✓
4	Beleuchtung Ladefläche	I	✓	✓	≥ 0,3Ω	✓	≥ 1MΩ	✓	≤ 3,5mA	✓		✓	≤ 0,5mA	✓
5														
6														
7														
8														
9														
10														
11														
12														
13														
14														

Prüfer: Bundil Norbert, Hauptamtlicher Gerätewart FF-Hersbruck

